


Top View

Bottom View

If flight controller hole alignments are skewed, bottom plate and mid plate orientation are incorrect. Ensure alignment before assembling.

Created by Pacific Flying Machines 1/10/2021		Approved by GateCrasher 1/10/2021	
Document type Build Sheet		Document status Released	
Title Hayabusa		DWG No. 001	
Rev. 01	Date of issue 1/10/2021	Sheet 1/2	



Created by Pacific Flying Machines 1/10/2021		Approved by GateCrasher 1/10/2021	
Document type Build Sheet		Document status Released	
Title Hayabusa		DWG No. 001	
Rev. 00	Date of issue 1/10/2021	Sheet 2/2	